

PRIORITY

OUT58134

TOP SECRET 020010Z

1966 APR 2 00 59Z

25X1

1. NUMERICAL SUMMARY

MSN NO AND DATES: 1030-1, 9-14 MARCH 1966
1030-2, 14-19 MARCH 1966

LAUNCH DATE AND TIME: 9 MARCH 1966/2202Z

VEHICLE NUMBER: 1622

CAMERA SYSTEM: J-29

PAN CAMERA NOS: FWD LOOKING (MASTER) 182
AFT LOOKING (SLAVE) 183

S/I CAMERA NOS: MSN 1030-1: D94/100/107
MSN 1030-2: D82/195/102

RECOVERY REVS: D81 AND D159

4 APR 1966

2. CAMERA SETTINGS

FWD LOOKING	Ø.275 INCH SLIT, WRATTEN 25 FILTER
AFT LOOKING	Ø.175 INCH SLIT, WRATTEN 21 FILTER

3. PERFORMANCE SUMMARY

A SMALL PORTION OF THE PAN PHOTOGRAPHY FROM THIS MISSION IS

TOP SECRET

SIO
 EDO
 DDO
 ISO
 PO
 PSD
 PSD-ICE
 TID
 SAR

 PAG
 DIAXX-4
 SPAQ
 NSA-LO
 DIA-AP

Advances in
Statistics

1. **Model 1**
2. **Model 2**
3. **Model 3**
4. **Model 4**
5. **Model 5**
6. **Model 6**
7. **Model 7**
8. **Model 8**
9. **Model 9**
10. **Model 10**
11. **Model 11**
12. **Model 12**
13. **Model 13**
14. **Model 14**
15. **Model 15**
16. **Model 16**
17. **Model 17**
18. **Model 18**
19. **Model 19**
20. **Model 20**
21. **Model 21**
22. **Model 22**
23. **Model 23**
24. **Model 24**
25. **Model 25**
26. **Model 26**
27. **Model 27**
28. **Model 28**
29. **Model 29**
30. **Model 30**
31. **Model 31**
32. **Model 32**
33. **Model 33**
34. **Model 34**
35. **Model 35**
36. **Model 36**
37. **Model 37**
38. **Model 38**
39. **Model 39**
40. **Model 40**
41. **Model 41**
42. **Model 42**
43. **Model 43**
44. **Model 44**
45. **Model 45**
46. **Model 46**
47. **Model 47**
48. **Model 48**
49. **Model 49**
50. **Model 50**
51. **Model 51**
52. **Model 52**
53. **Model 53**
54. **Model 54**
55. **Model 55**
56. **Model 56**
57. **Model 57**
58. **Model 58**
59. **Model 59**
60. **Model 60**
61. **Model 61**
62. **Model 62**
63. **Model 63**
64. **Model 64**
65. **Model 65**
66. **Model 66**
67. **Model 67**
68. **Model 68**
69. **Model 69**
70. **Model 70**
71. **Model 71**
72. **Model 72**
73. **Model 73**
74. **Model 74**
75. **Model 75**
76. **Model 76**
77. **Model 77**
78. **Model 78**
79. **Model 79**
80. **Model 80**
81. **Model 81**
82. **Model 82**
83. **Model 83**
84. **Model 84**
85. **Model 85**
86. **Model 86**
87. **Model 87**
88. **Model 88**
89. **Model 89**
90. **Model 90**
91. **Model 91**
92. **Model 92**
93. **Model 93**
94. **Model 94**
95. **Model 95**
96. **Model 96**
97. **Model 97**
98. **Model 98**
99. **Model 99**
100. **Model 100**

25X1

-2-

1

CONSIDERED TO BE AS GOOD AS ANY OBSERVED IN RECENT MISSIONS. HOWEVER, MOST OF THE MATERIAL WAS OF DISTINCTLY POORER QUALITY THAN ANY RECENT CORONA MISSION. THE REDUCTION IN OVERALL QUALITY IS ATTRIBUTED TO SEVERE ATMOSPHERIC CONDITIONS AND HIGH ORIGINAL NEGATIVE DENSITY. THESE CONDITIONS ARE DISCUSSED FURTHER IN PARA 5, COMMENTS.

ONLY ONE RESOLUTION TARGET DISPLAY WAS IMAGED. THIS HIGH CONTRAST TARGET, COVERED UNDER POOR WEATHER CONDITIONS, INDICATED ALONG TRACK (IMC) AND CROSS TRACK (SCAN) RESOLUTION VALUES OF ABOUT FOR BOTH CAMERAS. THE QUALITY OF MATERIAL FROM THE TWO PAN CAMERAS APPEARED ON THE AVERAGE TO BE COMPARABLE.

25X1

4. ANOMALIES

ANOMALIES INCLUDING THOSE REPORTED IN THE REBIND 42 MESSAGES (REF A, B, AND C) WERE REVIEWED.

A. POOR IMAGERY FROM STARBOARD HORIZON CAMERAS

CAUSE: THE STARBOARD H.O.'S PRODUCED POOR BUT USABLE IMAGERY VERY EARLY IN THE MISSION. AS THE FLIGHT PROGRESSED THE STARBOARD H.O.'S CONTINUED TO DEGRADE TO A USELESS CONDITION. THEY BEGAN TO CLEAR ON PASS D98, AND AFTER D132 APPEARANCE WAS NORMAL. IT IS NOTED THAT ON MISSIONS WHERE THE VEHICLE WAS NOT YAWED AROUND, NO DEGRADING EFFECTS WERE OBSERVED ON THE H.O.'S OR STELLAR CAMERA MATERIAL.

ACTION: NONE INDICATED ON THE BASIS OF PRESENT DATA.

B. MISSING END-OF-PASS MARK ON MASTER INSTRUMENT.

CAUSE: REVIEW OF THE PRE-FLIGHT MATERIAL INDICATED THAT

-3-

THE EOP MARK WAS PRESENT PRIOR TO LIFT OFF. THE MARKER LAMP WAS LOST DURING ASSENT, PROBABLY DUE TO VIBRATION SINCE IT WAS NOT PRESENT ON ANY FLIGHT PHOTOGRAPHY.

ACTION: NONE INDICATED.

C. AN EMULSION SCRATCH REPEATING AT 6 1/4 INCH INTERVALS WAS EVIDENT THROUGHOUT THE INDEX RECORD OF 1030-1. THE SCRATCH WAS LOCATED 5/8" FROM THE CAMERA NUMBER EDGE.

CAUSE: THIS IS A PROCESSOR DEFECT AND THE CAUSE OF THE PROBLEM HAS BEEN CORRECTED.

ACTION: NO FURTHER ACTION REQUIRED.

D. RAKE LINES IN THE LATTER PART OF 1030-1 AFT CAMERA MATERIAL.

CAUSE: THIS DEFECT COULD ORIGINATE IN MANUFACTURE, OPERATION, OR PROCESSING.

ACTION: UNDER INVESTIGATION.

25X1

E. CHARACTERISTIC ANOMALIES

THERE ARE CERTAIN CHARACTERISTIC ANOMALIES THAT ARE CONSIDERED INHERENT TO THE OPERATION OF THE CORONA SYSTEM. WHILE THESE ITEMS WARRANT ATTENTION TO PREVENT FURTHER DEGRADATION, IT IS NOT FELT THAT SPECIFIC ACTION ITEMS SHOULD BE ASSIGNED. A SUMMARY OF THESE ITEMS AND THE DEGREE OF DEGRADATION IS PRESENTED BELOW.

(1) SCRATCHES IN THE FORMATS OF BOTH PAN CAMERAS WERE NORMAL.

(2) RAIL SCRATCHES FROM BOTH PAN CAMERAS WERE NORMAL.

(3) RAGGED FORMAT EDGES FROM SCRAPED EMULSION WERE

- 4 -

GREATER THAN NORMAL.

(4) STATIC DISCHARGE ALONG THE EDGES OF BOTH PAN CAMERA FILMS WAS LESS THAN NORMAL.

(5) LIGHT LEAKS AFFECTING BOTH PAN CAMERA FILMS WERE LESS THAN USUAL.

(6) PLUS DENSITY ELECTROSTATIC STREAKS ON BOTH STELLAR FILMS WERE NORMAL.

(7) MULTI-DIRECTIONAL, PLUS DENSITY STREAKS APPEARED INTERMITTENTLY THROUGH FRAME 78 OF THE 1030-1 STELLAR MATERIAL. THIS CONDITION IS NORMAL.

5. COMMENTS

A. BOTH THE PET AND THE PI'S FEEL THAT THIS MISSION WAS BADLY AFFECTED BY ATMOSPHERICS. IN MANY TARGET AREAS THERE WAS A SEVERE HAZE LAYER THAT DRASTICALLY REDUCED CONTRAST AND IMAGE QUALITY. AN ANALYSIS OF THE INDEX MATERIAL BEARS THIS OUT. IN THIS ANALYSIS THE NUMBER OF CLEAR FRAMES WERE NOTED. THOSE WITH A HIGH PERCENTAGE OF CLOUDS OR OBVIOUS HAZE WERE NOT FURTHER ANALYZED. THOSE THAT WERE CLEAR WERE BROKEN DOWN INTO SNOW AND ICE, AND TERRAIN CATEGORIES. THE DATA PRESENTED BELOW CLEARLY ILLUSTRATES THE LOW PERCENTAGE OF CLEAR INDEX FRAMES OBSERVED, AND THE EVEN LOWER PERCENTAGE OF CLEAR TERRAIN FRAMES OBSERVED.

1030-1 (TOTAL INDEX FRAMES - 422)

TOTAL CLEAR FRAMES (10 PERCENT OR LESS CLOUD COVER)

65 OR 15 PERCENT

CLEAR (WITH SNOW AND ICE)

58 OR 13 PERCENT

-5-

CLEAR TERRAIN	7 OR 2 PERCENT
1030-2 (TOTAL INDEX FRAMES - 444)	
TOTAL CLEAR FRAMES (10 PERCENT OR LESS CLOUD COVER)	75 OR 17 PERCENT
CLEAR WITH SNOW AND ICE	23 OR 6 PERCENT
CLEAR TERRAIN	52 OR 11 PERCENT

FROM THIS ANALYSIS IT IS OBVIOUS THAT A VERY SMALL PERCENTAGE OF THE TARGETS WERE IN CLEAR AREAS.

B. ON MISSION 1030, THE MEASURED D-MIN VALUES WERE HIGHER THAN ON PREVIOUS CORONA MISSIONS, EVEN WITH A LOWER PERCENTAGE OF FULL PROCESSING. THE TEAM IS CONCERNED, BUT UNCERTAIN, AS TO THE SIGNIFICANCE OF THIS FACT. IT IS NOT EASY TO DEFINE WHAT IS AN OPTIMUM EXPOSURE, BECAUSE OF THE LACK OF CORRELATION BETWEEN MEASURED DENSITY VALUES AND MISSION PERFORMANCE. THE CORRELATION BETWEEN MEASURED DENSITY VALUES AND MISSION PERFORMANCE IS NOT A STRAIGHT FORWARD MATTER. VARIABLES SUCH AS ATMOSPHERICS, SLIT WIDTH, SOLAR ALTITUDE, LAUNCH TIME, ETC., CAN AFFECT BOTH DENSITY AND PERFORMANCE IN DIFFERENT WAYS. THE PET FEELS THAT UNTIL FURTHER RESEARCH REVEALS MORE SPECIFIC INFORMATION RELATING TO OPTIMUM EXPOSURE LEVELS, THIS QUESTION WILL REMAIN ESSENTIALLY UNANSWERABLE.

C. BECAUSE OF THE LACK OF CORRELATION BETWEEN MTF RESOLUTION DATA AND MISSION PERFORMANCE, THE TEAM RECOMMENDS THAT ☐ UNDER-TAKE A STUDY TO EVALUATE THE CORRELATION BETWEEN MTF RESOLUTION VALUES AND THE FACTORS RELATING TO THESE MEASUREMENTS.

-6-

D. THE PET RECOMMENDS THAT PROJECT MANAGEMENT CONSIDER THE USE OF A WRATTEN 23 FILTER IN PLACE OF THE WRATTEN 25 ON THE FWD LOOKING CAMERA. SUFFICIENT QUANTITY OF FILTER MATERIAL AND FILTER FACTOR INFORMATION HAVE BEEN SUPPLIED TO AP.

T O P S E C R E T

--END OF MESSAGE--

1